

## PROPERTIES 1

### **SURFACE QUALITY**

The interior and exterior surfaces of the piping must be clean and smooth.

Any residue left over after solvent has evaporated must not exceed 38 mg/m<sup>2</sup> of the internal surface.

